

Royal Vendors

1-800-321-8637

Vendor Model Number	Three Tube Coin Changer	Four Tube Coin Changer	Bill Acceptor	Bill Acceptor Switch 3	Remote Mount Board	Bill Acceptor Harness Required	Bracket Required	Controller Board Used	Free Vend Coupon
Merlin 2000 Ver.1	9302-L, 9302-LF	--	MAG30B	ON	NO	CA# 407419-1 AND 406958		Masterwork Electronics	NO
Merlin 2000 Ver.2	9302-L, 9302-LF	--	MAG30B	ON	NO	CA# 407419-1 AND 406958		Masterwork Electronics	NO
Merlin 2000 Ver.5	9302-L, 9302-LF	--	MAG30B <i>(Note 1)</i>	ON	NO	CA# 407604		Masterwork <i>(Note 5)</i>	NO
Merlin 3	9302-LF	--	MAG30B <i>(Note 1,2)</i>	ON	NO	CA# 407604	407747-3 (Coke only)	Masterwork Electronics	NO
Merlin 3 (MDB)	9302-GX	USQ-G700	MAG30B	ON or OFF	NO	CA# 407420	407747-3 (Coke only)	Masterwork Electronics	YES
Merlin 4 (MDB)	9302-GX	USQ-G700	MAG30B	ON or OFF	NO	CA# 407420	407747-3 (Coke only)	407862 408266	YES
Merlin TDV (MDB)	9302-GX	USQ-G700	MAG30B	ON or OFF	NO	CA# 407420	407747-3 (Coke only)	407862-1 408266-1	YES
G2 (MDB)	9302-GX	USQ-G700	MAG30B <i>(Note 3)</i>	ON or OFF	NO	CA# 407420 <i>(Note 3)</i>	407747-3	407306	YES
G3 (MDB)	9302-GX	USQ-G700	MAG30B	ON or OFF	NO	CA# 407420	407747-3	407543 408024	YES <i>(Note 4)</i>
G3 EVS (MDB) WAVE	9302-GX	USQ-G700	MAG50B, MAG52BX	ON or OFF	NO	CA# 407420	407747-3	407950-1	YES
KO TDV (MDB) WAVE	9302-GX	USQ-G700	MAG50B, MAG52BX	ON or OFF	NO	CA# 407420	407747-3	408084	YES
Single Price	9341-S, 9360-S 9370-S	USQ-S700	MAG30B	ON	NO	CA# 407052-1	--	--	NO
Milk Vendor	9302-GX	USQ-G700	MAG30B	ON or OFF		CA# 407420		408266-3	YES

Vendor Model Number	Three Tube Coin Changer	Four Tube Coin Changer	Bill Acceptor	Bill Acceptor Switch 3	Remote Mount Board	Bill Acceptor Harness Required	Bracket Required	Controller Board Used	Free Vend Coupon
EZ Vendor	9302-GX	USQ-G700	MAG30B	ON or OFF	NO	CA# 407420		408266-2	YES

NOTES:

1. MAG30SA interfaces using CA harness #407700, bill acceptor option switch #3 must be "OFF".
2. Controller board must have software revision 10.04 or 11.04 and newer, Center door changer machines with 9302-LF's require bill acceptor harnesses 407419-1 & 407179-1.
3. Controller board must have software 920940-8 or newer for MDB bill acceptors, use CA harness #407419 and 407179-1 for NON-MDB bill acceptors.
4. For controller board 407543, set bACC (Bill Acceptance Setting Mode) to "ALL".
5. Merlin 2 Version 5 can be converted to MDB by using a Merlin 3 control board and harness 842-079-041.