



## Currency Upgrades

The Federal Reserve periodically releases new bill designs to reduce counterfeiting. Due to changes in the design of the latest \$10 bill, all Coinco bill acceptors manufactured prior to March 1, 2006 (serial # beginning 0906xxxxx) will require an upgrade in order to accept the new currency.

The method in which your Coinco bill acceptor is upgraded depends upon the manufacture date. Upgrades range from a simple software flash via a Field Programmer to replacing the circuit board assembly.

To help determine the appropriate upgrade and pricing for your bill acceptor, please contact your local Coinco Service Center or call our Technical Support line at 1-800-325-2646.

### BillPro, MagPro, Mag & BA Upgrade Kits

The table below shows which acceptors will require upgrades. Installing these updates will automatically ensure that your acceptor not only accepts the new \$10 bill, but also all earlier currency updates.

Acceptor Serial Number	Applicability	Kit #	Kit Type	Flash Upgrade Required?
#0906XXXXX and newer	B, SA, & R Models	None Required	NA	No
#3903XXXXX to #0806XXXXX	B, SA, & R Models	None Required	NA	Yes
#3803XXXXX and earlier	B Model 110V	408076.20	Logic Board	No / Included
	B Model 24V	408049-2.15	Logic Board	No / Included
	SA Model	408190.15	Logic Board	No / Included
	R Model	408100.17	Logic Board	No / Included

Note: Logic Board changes will also require the use of # 921623 Calibration Paper.

### Programmer Usage for Software Updates

Model	Programmer	Notes
BillPro	FP-4	Software Flash
Mag / MagPro	FP-3	Software Flash
BA	FP-3	Software Flash
MC Series	Download Box	Replace E-Prom

Note: Upgrades are sold in minimum 10 count increments.